#### DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 69.28

## WELDING INSPECTION REPORT

Resident Engineer: Pursell, Gary **Report No:** WIR-011668 Address: 333 Burma Road **Date Inspected:** 06-Dec-2009

City: Oakland, CA 94607

**OSM Arrival Time:** 700 **Project Name:** SAS Superstructure **OSM Departure Time:** 900 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai China

**CWI Name: CWI Present:** Yes No Yes N/A **Rod Oven in Use:** Yes No **Inspected CWI report:** No N/A N/A N/A **Electrode to specification:** Yes No **Weld Procedures Followed:** Yes No N/A **Qualified Welders:** Yes No **Verified Joint Fit-up:** Yes No N/A N/A Yes No N/A **Approved Drawings:** Yes No **Approved WPS:** Yes No N/A **Delayed / Cancelled:** 

34-0006 **Bridge No: Component:** 

## **Summary of Items Observed:**

On this day Caltrans OSM Quality Assurance (QA) Inspector Daniel Barrentine was present during the times noted above for observations relative to the fabrication of the SAS Superstructure being performed by Zhen Hua Port Machinery Company (ZPMC) at Chang Xing Island in Shanghai, China. QA Inspector observed and/or found the following:

This QA Inspector performed in process inspections in the trial assembly yard and monitored weld repairs in the heavy dock area to include the use of preheat, proper welding procedure, and the presence of ABF QA and ZPMC CWI's.

This Inspector assisted in the execution of inspection request document number 004808. Items tested were contained in and pertaining to the South Tower, Lift 4 and identified as follows: SSTL4-1CL 32/91,SSTL4-1HL 21, SSTL4- 1GL 19/89, and SSTL4- 1FL 17/91. No recordable indications were noted.

## **Summary of Conversations:**

No relevant conversations.

#### **Comments**

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang 15000422372, who represents the Office of Structural Materials for your project.

# WELDING INSPECTION REPORT

(Continued Page 2 of 2)

Inspected By:	Barrentine, Daniel	Quality Assurance Inspector
Reviewed By:	Carreon, Albert	QA Reviewer